

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 01/15/2014
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 155715	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01, 04 B. WING _____		(X3) DATE SURVEY COMPLETED R 01/13/2014
NAME OF PROVIDER OR SUPPLIER LUTHERAN COMMUNITY HOME			STREET ADDRESS, CITY, STATE, ZIP CODE 111 W CHURCH AVE SEYMOUR, IN 47274		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
{K 000}	<p>INITIAL COMMENTS</p> <p>A Post Survey Revisit (PSR) to the Life Safety Code Recertification and State Licensure Survey conducted on 11/14/13 and 11/15/13 was conducted by the Indiana State Department of Health in accordance with 42 CFR 483.70(a).</p> <p>Survey Date: 01/13/14</p> <p>Facility Number: 000347 Provider Number: 155715 AIM Number: 100275440</p> <p>Surveyor: Mark Bugni, Life Safety Code Specialist</p> <p>At this PSR survey, Lutheran Community Home was found in compliance with Requirements for Participation in Medicare/Medicaid, 42 CFR Subpart 483.70(a), Life Safety from Fire and the 2000 edition of the National Fire Protection Association (NFPA) 101, Life Safety Code (LSC) and 410 IAC 16.2. The A Wing, B Wing, C Wing, D Wing, Front Entrance/Main Dining Room Wing, and Service Hall Wing were surveyed with Chapter 19, Existing Health Care Occupancies.</p> <p>This one story facility was determined to be of Type II (222) construction and fully sprinkled. The facility has a fire alarm system with smoke detection in the corridors, in spaces open to the corridors, and battery operated smoke detectors in all resident sleeping rooms. The facility has a capacity of 109 and had a census of 102 at the time of this visit.</p> <p>All areas where the residents have customary access were sprinkled. All areas providing facility</p>	{K 000}			

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 01/15/2014
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 155715	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01, 04 B. WING _____		(X3) DATE SURVEY COMPLETED R 01/13/2014
NAME OF PROVIDER OR SUPPLIER LUTHERAN COMMUNITY HOME			STREET ADDRESS, CITY, STATE, ZIP CODE 111 W CHURCH AVE SEYMOUR, IN 47274		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
{K 000}	Continued From page 1 services were sprinkled, except an eighteen foot by sixteen foot wood framed detached storage building.	{K 000}			
{K 000}	Quality Review by Robert Booher, Life Safety Code Specialist-Medical Surveyor on 01/14/14. INITIAL COMMENTS A Post Survey Revisit (PSR) to the Life Safety Code Recertification and State Licensure Survey conducted on 11/14/13 and 11/15/13 was conducted by the Indiana State Department of Health in accordance with 42 CFR 483.70(a). Survey Date: 01/13/14 Facility Number: 000347 Provider Number: 155715 AIM Number: 100275440 Surveyor: Mark Bugni, Life Safety Code Specialist At this PSR survey, Lutheran Community Home was found in compliance with Requirements for Participation in Medicare/Medicaid, 42 CFR Subpart 483.70(a), Life Safety from Fire and the 2000 edition of the National Fire Protection Association (NFPA) 101, Life Safety Code (LSC) and 410 IAC 16.2. The 2010 C Wing addition was surveyed with Chapter 18, New Health Care Occupancies. This 2010 addition to the one story facility was determined to be of Type II (222) construction and fully sprinkled. The facility has a fire alarm system with smoke detection in the corridors, in spaces open to the corridors, and battery	{K 000}			

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 01/15/2014
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 155715	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01, 04 B. WING _____		(X3) DATE SURVEY COMPLETED R 01/13/2014
NAME OF PROVIDER OR SUPPLIER LUTHERAN COMMUNITY HOME			STREET ADDRESS, CITY, STATE, ZIP CODE 111 W CHURCH AVE SEYMOUR, IN 47274		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
{K 000}	Continued From page 2 operated smoke detectors in all resident rooms. The facility has a capacity of 109 and had a census of 102 at the time of this visit. All areas where the residents have customary access were sprinkled. All areas providing facility services were sprinkled, except an eighteen by sixty six foot wood framed detached storage building.	{K 000}			